

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: 27/05/2024

It is certified that the existing building TRINITY HIGH SCHOOL (name of the building or premises) at DHOOLKOT, DEHRADUN (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	2 (1+1)	-	-	-	-	-

The building is owned/occupied by TRINITY HIGH SCHOOL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of (Name of Department/ Govt.) on 24/05/2024 (date of inspection) in the presence of RAJAN AGRAWAL, 96SHIPRA VIHAR, CANAL ROAD, DEHRADUN (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 2013 for a period of 11 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Evaluation of structural stability of building every 3 years.
2. Periodic maintenance every year or earlier if required.
3. Information to be provided of additional construction or charges.
4. Charges if required to be duly certified by structural engineers.

Issued on 27/05/2024 at 11:30 am by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: Suneet Prasad

Name: (SUNEET PRASAD)

Designation: CONSULTING ENGINEER

Name & Address of Department/ Office: _____